

## Signtac Design Guidelines



AVOID: COMPLEX AND JAGGED LINES, THESE CAN CREATE EASY LIFTING EDGES AIM FOR: SMOOTH FLOWING LINES, AS SIMPLE AS POSSIBLE



AVOID: NECKING, IT WILL MAKE THE MATERIAL WEAK ACROSS THE NARROWEST POINT AVOID: HOLES IN THE ARTWORK AS IT WILL MAKE THE MATERIAL WEAK AIM FOR: SHAPES THAT AREN'T WIDER AT THE EXTREMITIES

